

An External Contractor

Order No. SAD00002

Chine Walk Playground (Ferndown)

Address Chine Walk
West Parley
BH22 8PX

Supervisor
Darron C Pitman 01202 890659



Manufacturer GL Jones Engineering Ltd
Supplier GL Jones Engineering Ltd

Fault Identified 28/01/2005
Item Rocking Horse - C003
Surface Wet Pour
Problem Repair Loose Gator



Risk Level : 5 - Very Low The rear gator may require repair by a specialist.

Notice when printed how the images are perfectly sized and also displays the inventory item to which this defect applies. Note also how small the small file size of this PDF is - important when emailing...